

# Electronice Control Modules (ECU)

## TPMS Tyre pressure monitoring system will not activate

### Issue

Tyre pressure warning system cannot be activated, The tyre pressure warning system cannot be activated in the MMI (goes straight to off after switching it on).

### Technical Background

Only vehicles with software version 270 are affected.

From software 270 activation/deactivation must not be possible any more. If the above phenomenon occurs, the control unit has switched to a developer software mode.

The problem is caused by the software, do not replace any components.

[See the full details here](#)

Unique solution ID: #1054

Author: Nick

Last update: 2013-04-26 00:34