

Interior Electrics

Remote has poor range Radio has poor reception

Problem

Range of the remote control too low.
Range of the remote control for the auxiliary heater too low.
Poor radio reception.

Technical background

The spring contacts in the aerial module have no contact with the rear screen (aerial).

Production change

Optimised spring contacts in the aerial module.

Resolution

Check whether the problem is resolved by pressing against the aerial module.

Also check the reception level for changes.

Audi A8 (4E):

Observe the reception level in the K-Box (address 56) in the measured value block 06.

If pressing the aerial module improves the situation, replace please the aerial module.

Unique solution ID: #1026

Author: Nick

Last update: 2013-02-22 21:48