

# Interior Electrics

## Multi-function steering wheel: MMI operation doesn't work

### Problem

One or several buttons or adjustment wheels of the multi-function steering wheel do not work. After the final control diagnosis in the steering wheel electronics (address code 16) the buttons / adjustment wheels are fully operational again.

### Technical background

Missing adjustment in the control unit for display and operating unit.

### Resolution

Adjust channel 1 of the multi-function steering wheel in the control unit for display and operating unit (address code 07).

Unique solution ID: #1033

Author: Nick

Last update: 2013-02-22 23:09