

Interior Electrics

Voice control, Beeps and says Cancel

Problem

After pressing the button for activating the voice operation on the steering wheel the confirmation sound "PING" is heard and the announcement "Cancel" is made straight away.

The dialogue is broken off and the voice operation system cannot be operated any more.

Technical background

The component protection for the voice control unit (address 67) is active, but there is **no** entry in the control unit for voice operation. Hence, the guided fault finding does not automatically provide the action "Programme component protection".

Production change

Software update.

Resolution

The component protection for the voice control unit (address 67) must be reprogrammed with the guided functions or the following test programmes:

This needs to be done at an Audi dealer

Unique solution ID: #1039

Author: Nick

Last update: 2013-02-23 08:47